


Note: There are no jumpers or dip switches on this board.



(RJS/jlc-03/28/94)